

[Відкриті аукціони](#) [Закриті аукціони](#) [Аукціони «Купити зараз»](#)



Opel Insignia 1,6 "Sport"

Дата закриття аукціону:	2025-04-02 15:45:00
id:	11709925
Країна, де знаходиться авто	Німеччина
Адреса місця видачі авто	Chemiczna 15, 22-100, Chełm, Польща
Пробіг	99,500 тис.км
Дата першої реєстрації	01-09-2009
Коробка передач	Ручна/Механіка
Тип палива	Бензин
Робочий об'єм двигуна	1600 см ³
Потужність двигуна	132 kw
Назва сайту-аукціону	Autobid

Комплектація

Vehicle Extras, Add-ons and Accessories

- ABS
- Adaptive Forward Lighting (AFL)
- Airbags: 4
- Autobeam
- Automatic dimming exterior mirror
- Automatic dimming internal mirror
- Bi-xenon
- Climatronic
- Cruise control
- Electric windows front
- Fog light
- Heated external mirror
- Leather steering wheel
- MP3, Radio, CD
- Multi-function steering wheel
- On-board computer
- Parking aid PDC (Park Distance Control) rear
- Power steering
- Rain sensor
- Remote central locking
- Satnav with map views: DVD 800 Navi
- Side mirror electrically foldable
- Stability program ESP (Electronic Stability Program)

Vehicle Extras, Add-ons and Accessories

• Bi-Xenon-Scheinwerfer mit adaptiver Lichtverteilung (AFL) (Fahrassistenz-System: Fernlichtassistent, Aktives Kurvenlicht (AFL)) Parkpilotsystem Sicht-Paket Sitz-Komfort-Paket 2 (Sitz-Komfort-Paket 1, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Premium-Sitz vorn rechts, Lendenwirbelstütze Sitz vorn rechts, elektr. verstellbar)

Seats

- Number of seats 5
- Fabric: anthracite grey, anthracite grey
- Centre armrest: front and rear
- Split rear seat

Коментарі

Start price: 800 €

Vehicle Documents

- Type of ownership certificate: Motor vehicle registration certificate (part II)
- Sending of vehicle documents: The sending of the Motor vehicle registration certificate (part II) will take place at the earliest 10 working day(s) after receipt of payment.
- Vehicle document handling: 15 Euro netto
- Number of keys: 2

Identified Defects

- Engine: Noises - diagnostics necessary
- Further technical deficiencies: Clutch grinding, gearbox noises

Accident / Prior Damage

- **Existing damage:**
- Accident damage front left,
- Damage amount: Amount unknown

Other interior defects:

- Traces of use

Other bodywork damage:

- Engine compartment insulation damaged

Умови аукціону

Документи на автомобіль будуть видані разом із автомобілем.