

[Відкриті аукціони](#) [Закриті аукціони](#) [Аукціони «Купити зараз»](#)



VW Touran 1,2 TSI BMT "Comfortline"

Дата закриття аукціону:	2025-04-09 10:45:00
id:	11782274
Країна, де знаходиться авто	Німеччина
Адреса місця видачі авто	Chemiczna 15, 22-100, Chełm, Польща
Пробіг	132,400 тис.км
Дата першої реєстрації	01-12-2015
Коробка передач	Ручна/Механіка
Тип палива	Бензин
Робочий об'єм двигуна	1200 см ³
Потужність двигуна	81 kw
Назва сайту-аукціону	Autobid

Комплектація

Vehicle Extras, Add-ons and Accessories

- ABS
- AC
- Airbags: 6
- Auto Hold
- Electric windows front and rear
- Heated external mirror
- Leather steering wheel
- On-board computer
- Parking aid APS (Acoustic Parking System) front/rear
- Radio, CD, MP3 Composition Media (Touchscreen, Radio/CD-Player, MP3, Bluetooth)
- Remote central locking
- Roof rails
- Satnav with map views
- Servotronic
- Side mirror electrically adjustable
- Stability program ASR (Anti-Slip Regulation), TCS (Traction Control System)
- Start/stop system
- Telephone: Preparation with Bluetooth
- Tinted rear windows
- Touchscreen
- Tyre Pressure Indicator TPI

Vehicle Extras, Add-ons and Accessories

- Antennen-Diversity Mobile Online Dienste Car-Net

Special Extras

- Auto-Hold-Function
- Chrome package I
- Fatigue detection
- Multimedia connector AUX/Media-IN
- Tempowarnung
- USB-interface

Seats

- Number of seats 5
- Fabric: anthracite grey
- Sitzbezüge in Stoff, Dessin 'Lasano' Titanschwarz
- Centre armrest: front
- Split rear seat
- Pass-through option

Коментарі

Start price: 8500 €

Vehicle Documents

- Type of ownership certificate: Certificate of Conformity
- Sending of vehicle documents: The sending of the Certificate of Conformity will take place at the earliest 10 working day(s) after receipt of payment.
- Certificate of Conformity: Not available
- Vehicle document handling: 15 Euro netto
- Number of keys: 1
- Service certificate: available
- Latest inspection at: 07.2024
- Last inspection at: 122.199 Kilometres, All inspections performed at a manufacturer-authorized workshop.
- Next general inspection (HU) due: 12.2024, Proof not available
- Exhaust gas inspection until: 12.2024, Proof not available

Identified Defects

- Brake system: Rear brakes worn

Accident / Prior Damage

- **Repaired previous damages:**
- Nachlackierung - Tür hinten rechts
- Damage amount: Amount unknown

Other interior defects:

- Traces of use
- Gear shift knob is worn

Other bodywork damage:

- The vehicle has various scratches and defects on the surface
- Various repaints
- Scratches from car wash

Умови аукціону

Документи на автомобіль будуть видані разом із автомобілем.

<https://auctionautoplace.com>

+38 093 170 8621