

[Відкриті аукціони](#) [Закриті аукціони](#) [Аукціони «Купити зараз»](#)



VOLKSWAGEN CRAFTER

Дата закриття аукціону:	2025-04-11 09:45:00
id:	11806680
Країна, де знаходиться авто	Бельгія
Адреса місця видачі авто	Chemiczna 15, 22-100, Chełm, Польща
Пробіг	21,900 тис.км
Дата першої реєстрації	11-01-2023
Коробка передач	Ручна/Механіка
Тип палива	Дизель
Робочий об'єм двигуна	1968 см ³
Назва сайту-аукціону	Vdfinmarketing

Комплектація

Crafter 2.0 CR TDi L3H3 75 kw.

ZR8:

ZI7:

Y48:

WF7:

U9B: 2 Usb Interfaces (type C) In Dashboard

U500:

U129:

R26:

QH1: Voice Control

QE4: Storage Package 2: Overhead Storage Compartment With Two 1-Din Slots And Reading Light

NZ2: Ecall Emergency System

N0C: Seat Trim Covers In Leatherette 'mesh'

KH6: Air Conditioning System With Manual Control In Cab

ER1: Regional Code ' Ece ' For Radio

EL5: Online Service, With Ocu, With Head Unit Coding, Without Engine Immobilizer Interconnection

B02: Type Approval Country Belgium

9ZX: Mobile Phone Interface

9WJ: Wired & Wireless App-Connect

9CW: Load Compartment Lighting: 4 Led Spots

8RE: 4 Speakers: 2 Tweeters, 2 Woofers

8F1: Side Marker Lamps

8AR: Navigation System Preparation

7UF: Radio Navigation System 'discover Media' With 20.3-Cm (8-Inch) Touch Screen

6XN: Exterior Mirrors, Power-Adjustable And Heated

6N2: Mud Flaps In Front And Rear

4Z3: Illuminated Glove Compartment With Lockable Lid

3TE: Comfort Seat On The Left, In 1st Row Of Seats

3SS: 2-Seater Front Passenger Bench On The Right With Storage Compartment And Folding Backrest With Table

3R2: High Roof, Outside Painted In Body Color

3QC: 3-Point Seat Belt With Seat Belt Height Adjustment In Front And Electric Seat Belt Pretensioner For The Driver

1S1: Tool Kit And Jack

1G2: Spare Wheel (steel Wheel) With Original Equipment Tire

1EV: Special Identification Label For Ec For Commercial Vehicles

1D1: Rigid Trailer Hitch (incl. Trailer Stabilization)

0VE: Information Kit In Flemish/french

GPS Storage: : Gps Storage:

Коментарі

Bodywork: Damaged

EN - porte arrière droite: Bad reparation

EN - porte avant droite: Bad reparation

: Broken

Interior: Damaged

+38 093 170 8621