

[Відкриті аукціони](#) [Закриті аукціони](#) [Аукціони «Купити зараз»](#)



Mercedes-Benz B 180

Дата закрытия аукциона:	2025-03-31 12:45:00
id:	11736191
Страна, где находится авто	Германия
Адрес места выдачи авто	Chemiczna 15, 22-100, Chełm, Польша
Пробег	87,200 тыс.км
Дата первой регистрации	01-03-2015
Коробка передач	Автомат
Тип топлива	Бензин
Рабочий объем двигателя	1600 см ³
Мощность двигателя	90 kw
Название сайта-аукциона	Autobid

Комплектация

Vehicle Extras, Add-ons and Accessories

- ABS
- AC
- Automatic dimming internal mirror
- Cruise control
- Electric windows front and rear
- Heated external mirror
- Leather steering wheel
- Multi-function steering wheel
- On-board computer
- Paddle shift steering wheel
- Parameter steering
- Parking aid ex works front/rear
- Radio, CD
- Rain sensor
- Remote central locking
- Satnav with map views
- Side mirror electrically foldable
- Stability program ASR (Anti-Slip Regulation), TCS (Traction Control System)
- Start/stop system
- Telephone: Preparation with Bluetooth
- Trailer coupling swivel-mounted
- Tyre Pressure Indicator TPI

Special Extras

- Adaptive brake (auto hold)
- Attention Assist
- Light & sight package
- Seatcomfort package

Seats

- Number of seats 5
- Fabric: anthracite grey, black
- Centre armrest: front and rear
- Split rear seat

Комментарии

Start price: 11500 €

Vehicle Documents

- Type of ownership certificate: Motor vehicle registration certificate (part II)
- Sending of vehicle documents: The sending of the Motor vehicle registration certificate (part II) will take place at the earliest 5 working day(s) after receipt of payment.
- Vehicle document handling: 15 Euro netto
- Number of keys: 2
- Next general inspection (HU) due: 03.2026, Proof available
- Exhaust gas inspection until: 03.2026, Proof available

General Information

- Tirefit Füllmittel - abgelaufen

Accident / Prior Damage

- **Repaired previous damages:**
- Schweller rechts, Tür hinten rechts, Tür vorne rechts, fachgerecht ausgeführt, Kotflügel rechts, Seitenwand rechts, nicht fachgerecht ausgeführt
- Damage amount: Amount unknown

Missing Part

- Service record

Other interior defects:

- Traces of use
- Steckdose - gebrochen

Other bodywork damage:

- The vehicle has various scratches and defects on the surface
- Various repaints
- Scratches from car wash

Умови аукціону

Документи на автомобіль будуть видані вместе с автомобилем.